

Glass felt Precoated/-pasted

Flügger felt and tissue for installation on walls and ceilings. Provides an aesthetic look with or without pattern depending on design chosen. Enhances the surface and counteracts cracking. Finished with paint in desired gloss and colour.



Properties

Precoated/-pasted glass tissue for installation on walls. Weight 145 g/m². Easy installation. Saturated surface that normally does not require primer.

- **Easy installation**
- **Enhances surface**
- **Counteracts cracking**

Use

Living rooms/common rooms, hallways and entrance areas, offices, kitchens, toilets, commercial premises, clinics and shops. Not suitable for surfaces requiring wet room water- and damp-proofing. Concrete, light concrete, plaster, plasterboard and gypsum fibre board.

Substrate

Must be clean, dry, firm and suitable for surface treatment.

Treatment

Remove loose material and paint by cleaning and sanding. Remove existing wallpaper. Remove dirt, grime, grease and chalking materials by cleaning. Water-soluble discolouration, nicotine and soot are cleaned and treated with blocking primer. Hard, smooth substrates should be sanded to a matt finish and painted with primer. Smooth out cracks, unevenness and holes with filler. Paint absorbent and porous substrates with primer.

Application

The glass tissue panels are cut into full lengths corresponding to the surface to be covered, + 10 cm for trimming. Activate the glue by pulling the glass tissue panel through a tub of water. Install the panels edge to edge. Remove air bubbles using a wallpaper spatula. Cut away the excess glass felt against adjacent surfaces. Wipe off excess adhesive with a sponge and lukewarm water. Always test adhesion and result before hanging

Expected result

Uniform, smooth surface. The surface may have some unevenness. Finish treat with paint in desired gloss and colour. Best results reached after two coats. Avoid placing loads on the surface before the treatment is fully cured.

Usefull Information

Prepasted

Please note!

Ensure good ventilation during and after hanging.

Supplemental Text

Remove as much adhesive as possible from brushes before washing them in water. Do not pour residue/remains of paint down the drain; take it to your local recycling centre. Minimise your paint waste by calculating how much paint you need in advance. Store leftover paint properly so the remains can be reused, which minimises the environmental impact.

Technical Data

Produkttype	Felt and Tissue
Cleaning of tools etc.	Water
Working temperature	Min. +10°C

Current TDS Version

February 2021

Replaces TDS Version

December 2021